

JLC-HCAL

tile-fiber module

systematic error

Pb plate thickness

$$\sigma/E < 0.6\% \text{ at } 2\text{GeV } \pi$$
$$< 0.5\% \text{ at } 1\text{GeV } e$$

